

Friday, May 06, 2016 9:08:00 AM

Page 1

Accept

Setup Start *NS1*

Stop *NS2*

Stop *NS2*

Cust Item ID:

Customer:

Run Start *NR1*

Stop ***NR2***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Draw Nbr	Revision Nbr
IIN D412-698	Rev E

100

Document Control

0.00

MAY 14 2016

DAG
6

9-89

ML5 160517

100

DOCUMENT CONTROL

DC

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile and create labels per PPP D412-698-013CHG001

2x 27

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

2x MAY 14 201

DAS	DAS
6	28
9-89	9-89

120

QC4- 100% Inspect kits for completeness

0.00

120

OC

Memo

0.06

Quality Control

2x

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY			
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong		
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions		
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance		
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect		
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing		
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved		
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing		
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish		
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread		
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence		
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____					
Misidentified ☐	☐ Past Due						

Work Order ID 145526

Friday, May 06, 2016 9:08:00 AM

145526

Page 2

Item ID: D412-698-013

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Cabin Door Handle -Aluminum Door

Start Date: 4/27/2016 Start Qty: 2.00 ***2***

Cust Item ID:

Required Date: 5/5/2016 Req'd Qty: 2.00 ***2***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
130	Packaging					2x DAS 28 9-89		MAY 20 2016	
Packaging	Memo Identify and pack for shipping as per PPP D412-698-013 Location: FG022	0.00							
140	QC21- Final Inspection - Work Order Release	0.00							
140								MAY 24 2016	
QC	Memo	0.20							
Quality Control									

MAY 24 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐							
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval				
Description Work Order Deviation				Disposition				Completed By			
								Lead hand / Supervisor Approval Verification			
								QC / QA Coordinator Approval			
Root Cause				FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐		No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐		Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐		Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	
				OTHER : ☐							

Friday, May 06, 2016 9:08:00 AM

Page 1

145526

D412-698-013

Required Date: 5/5/2016

Required Qty: 2.00

Comments: IPP Rev: C Removed Manufacturing 05-11-06 JLM
IPP Rev:D change to rev D ECN 1104 08-01-28 DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3203-1		Manufactured	No				Each	28.0000		8			
D3203-1 Handle DAS 27 9-89										**		DAS 6 28 9-89 9-89	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST484				28					
				135844				4					
				138058				12					
				142048				12					
D3220-041		Manufactured	No				Each	7.0000		2			
D3220-041 Doubler Assembly DAS 27 9-89										**		DAS 6 28 9-89 9-89	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST485				7					
				140231				7					
D3220-042		Manufactured	No				Each	7.0000		2			
D3220-042 Doubler Assembly DAS 27 9-89										**		DAS 6 28 9-89 9-89	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST485				7					
				140140				7					
D3220-3		Manufactured	No				Each	15.0000		4			
D3220-3 Doubler DAS 27 9-89										**		DAS 6 28 9-89 9-89	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST485				15					
				140035				15					

MAY 17 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY																																																												
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	No Re-verification ☐	Operator ☐	Offset/Setup ☐	Supplier ☐	Training ☐	Use for Testing ☐	Poor Information ☐	Rushing ☐	Product Improvement ☐	Process Improvement ☐	Manufacturing Process ☐	Past Due ☐	Pressure/Forced ☐	Bending ☐	Centre Not Concentric ☐	Cracks ☐	Crimp/Kink/Ripple/Wave ☐	Cuffs ☐	Crushing ☐	Heat Treat ☐	Wave/Twist in Tube ☐	Marks/Chatter ☐	Temperature/Cure ☐	Set-up ☐	BOM/Route ☐	Broken/Damage/Defect ☐	Inspection Incomplete/Unqualified ☐	Contamination ☐	Countersink ☐	Cut Too Short ☐	Instructions Incomplete/Unclear ☐	Drill Holes ☐	Power Loss/Surge ☐	Folio/Program ☐	Grain ☐	Weld ☐	Wrong Stock Pulled ☐	Out of Sequence ☐	Off-set ☐	Mislabeled ☐	Fit/Function ☐	Misaligned/off center ☐	Positioned Wrong ☐	Outside Dimensions ☐	Over/Under tolerance ☐	Part Incorrect ☐	Part Lost/Missing ☐	Part Moved ☐	Drawing ☐	Finish ☐	Misread ☐	Turning Sequence ☐
OTHER : ☐																																																															

Picklist Print

Friday, May 06, 2016 9:08:00 AM

Page 2

Work Order ID: 145526

145526

Parent Item: D412-698-013

D412-698-013

Parent Item Name: Cabin Door Handle -Aluminum Door

Start Date: 4/27/2016

Required Date: 5/5/2016

Start Qty: 2.00

Required Qty: 2.00

MS21042L4

Purchased

No

Each

1,670.000

8

16

MS21042L4

Locknut

**

DAS

DAS

6

28

9-89

9-89

Location

Loc Qty

Loc Code

GA

279

m133769

279

OVER007

500

m134676

500

ST303

794

m134606

794

ST305

97

m130922

97

DAS
27
9-89

MS24694-S98

Purchased

No

Each

312.0000

16

32

MS24694-S98

Screw

**

DAS

DAS

6

28

9-89

9-89

Location

Loc Qty

Loc Code

over006

250

m134134

100

m134502

150

ST283

62

m133990

62

DAS
27
9-89

NAS1149D0416J

Purchased

No

Each

4,234.000

8

16

NAS1149D0416J

WASHER

**

DAS

DAS

6

28

9-89

9-89

Location

Loc Qty

Loc Code

GA

222

m131511

222

ST260a

1984

m131511

1984

ST264

2028

m131511

2028

DAS
27
9-89

DAS

6

9-89

Friday, May 06, 2016 9:08:00 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER : _____							

6.0 PARTS LIST - CABIN DOOR MODIFICATION KITS

(FOR AIRCRAFT EQUIPPED WITH P/N 205-032-669-XXX ALUMINUM DOORS)

Qty -011	Qty -012	Qty -013	Qty -017	Qty -019	Qty -021	Part Number	Description
X						D412-698-011	CABIN DOOR ROLLER KIT, LH
	X					D412-698-012	CABIN DOOR ROLLER KIT, RH
		X				D412-698-013	DOOR HANDLE KIT
			X			D412-698-017	REPLACEMENT DOOR TRACK KIT
				X		D412-698-019	BEARING OVERHAUL KIT
					X	D412-698-021	REPLACEMENT SHIM KIT
3	3					D3121-141	BRACKET ASSEMBLY
1						D3121-143	BRACKET ASSEMBLY
	1					D3121-144	BRACKET ASSEMBLY
1	1					D3137-043	BRACKET ASSEMBLY
1						D3183-043	BRACKET ASSEMBLY
	1					D3183-044	BRACKET ASSEMBLY
9	9		9			D3199-1	BRACKET
1	1		1			D3202-1	COVER
		4				D3203-1	HANDLE
		1				D3220-041	DOUBLER
		1				D3220-042	DOUBLER
		2				D3220-3	DOUBLER
				7		D3121-21	BOLT
				5		D3121-241	BEARING ASSEMBLY
				1		D3137-3	GUIDE
				1		D3137-5	WASHER
				2		D3183-045	BEARING ASSEMBLY
					3	D3238-1	SHIM
					1	D3238-3	SHIM
					2	D3238-5	SHIM
					6	D3238-11	SHIM
					2	D3238-13	SHIM
					4	D3238-15	SHIM
		8				AN960JD416L	WASHER
		8				MS21042L4	NUT (OR MS21042-4)
		16				MS24694-S98	SCREW
				1		MS24694-S101	SCREW

• COPYRIGHT © 2003 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: **E**

Date: 08.05.01